



大埔郊野徑是連接沙羅洞和八仙嶺郊野公園的一段路徑，早前由於頻繁的使用和風化遭受了嚴重的侵蝕。為了改善情況並保護自然風貌，鄉郊辦試驗以手作步道手法及重用土木工程拓展署填料庫的廢石修復路徑。鄉郊辦期望以修復大埔郊野徑的經驗改善在沙羅洞中的步道。

The Tai Po Country Trail, a hiking trail connecting Sha Lo Tung and Pat Sin Leng Country Park, had suffered severe erosion due to frequent use and weathering. To improve the situation and protect the natural landscape, the Countryside Conservation Office carried out a experimented restoration to the trail with the use of handmade technique and waste rock from the Civil Engineering Department's Fill Bank.



將軍澳填料庫 TKO FILL BANK

由於現場附近找不到合適的材料，因此採用了升級回收的方法。修復工程所使用的**所有石頭均取自將軍澳土木工程拓展署填料庫**。考慮到手作限制，團隊在填料庫特別揀選擇了直徑 300 毫米左右的石頭。


An upcycling approach was adopted as no available materials could be found near the site. All the boulders used in the restoration were obtained from CEDD Fill Bank in Tsung Kwan O. Boulders around 300mm diameters was selected in views of the limited access to the site and workability.

~300MM



PHOTO GALLERY

照片庫



2021

4

6

8

A

B

C

D

5

7

9



2021

5

6

8



5


7

9



現場已經做了四種不同的修復。
Four different types of restoration have been carried on site.





現場已經做了四種不同的修復。
Four different types of restoration have been carried on site.